

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

**Adin Community Service District**

---

**Ash Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Dry Creek**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## DWR Sutter Maintenance Yard

---

### Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Fairfield Suisun Sewer District

---

### Laurel Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Ledgewood Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### McCoy Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Union Avenue Diversion

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Madera County FCWCA

### Ash Slough

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	M *
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

### Berenda Slough

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Chowchilla River

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Fresno River

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Merced Streams Group

### Bear Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Black Rascal Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Burns Creek

Overall Unit Rating	Rated Item	Item Rating
<b>U</b>	Vegetation & Obstructions	U
	Shoaling / Sedimentation	U
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Mariposa Creek & Duck Slough

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	M

### Miles Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	U
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### Owens Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Placer County

---

### Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## San Joaquin County Flood Control and Water Conservation District

### Duck Creek Diversion Channel

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

### North Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	M *

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

### South Littlejohn Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M *</b>	Vegetation & Obstructions	M *
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

\* Overall channel rating average is less than 0.2, however, U rated issues are present, so the overall rating is M instead of A.

### South Littlejohn Creek North Branch

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	M
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

**Flood Control Project Maintenance**  
**2018 Channel Summary Report**  
**Overall Unit and Item Ratings**

## Tehama County Fld Control & Water Cons Dist

---

### McClure Creek

Overall Unit Rating	Rated Item	Item Rating
<b>M</b>	Vegetation & Obstructions	M
	Shoaling / Sedimentation	M
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	N
	Encroachments	A

### Salt Creek

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A